

State Water Resources Control Board

August 18, 2017

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 1520 0001 7928 4536

Mr. Mark Gallagher
Environmental Manager
Yosemite Hospitality
P. O. Box 306
Yosemite, California 95389
gallagher-mark@aramark.com

**SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEM
LOCATED AT YOSEMITE HOSPITALITY - KITCHEN, 9018 YOSEMITE LODGE
DRIVE, YOSEMITE NATIONAL PARK**

Dear Mr. Gallagher:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on August 9, 2017, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and California Code of Regulations (CCR), title 23, chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Plot Plan/Site Map – An approved plot plan/site map indicating the location of the product piping, tanks, and auxiliary equipment with respect to buildings or other landmarks, such as the street was not available in CERS or onsite at the time of the inspection.	Diesel	August 9, 2017	Ongoing	H&SC 25286(a); 23 CCR 2711(a)(8)
2	Failure to Maintain Tank Information (Form B) – The tank information page in CERS needs to be updated because the piping is listed as conventional suction. The most recent annual monitoring certification and the service technician reported the piping as safe suction.	Diesel	August 9, 2017	Ongoing	23 CCR 2711(a)

No.	Violation	Tank	Start Date	Stop Date	Regulation
3	Failure to Monitor Product Piping – The sensor in the piping sump was unable to detect a leak at the earliest opportunity because it was not placed in a vertical position and at the lowest point in the sump. This was corrected at the time of inspection.	Diesel	August 9, 2017	August 9, 2017	23 CCR 2630(d)
4	Failure to Maintain Spill Containment Requirements – The spill containment structure contained either liquid or debris preventing its ability to hold five gallons.	Diesel	August 9, 2017	Ongoing	23 CCR 2635(b)(1)
5	Failure to Meet Design and Construction Requirements for Safe Suction Piping – To meet design and construction requirements for safe suction piping, no valves or pumps are installed below grade in the suction line and only one check valve is located directly below and as close as practical to the suction pump. A ball-valve on the product lines located within the tank access manway was observed at the time of the inspection.	Diesel	August 9, 2017	Ongoing	23 CCR 2636(a)(3)(C)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and the Mariposa County Public Health Department within sixty (60) days from the date of this letter. Have your DO make specific notations in the next monthly DO report indicating the ongoing violations have been corrected. The monthly DO report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Mr. Will Speth
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
801 K Street, Suite 2300
Sacramento, California 95814
will.speth@waterboards.ca.gov

Local CUPA

Ms. Carolyn Coder
Registered Environmental Health Specialist
Mariposa County Public Health Department
5100 Bullion Street
Mariposa, California 95338
ccoder@mariposacounty.org

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,



Amantha Henkel
Senior Environmental Scientist
UST Enforcement Unit
Office of Enforcement

cc: (via email only)

Ms. Rebecca Thompson
Director of Sustainability, Safety and Compliance
Yosemite Hospitality
thompson-rebecca1@aramark.com

Ms. Amy Grove
Compliance Coordinator
Yosemite Hospitality
grove-amy@aramark.com

Mr. James Samual
Director of Transportation
Yosemite Hospitality
samual-james@aramark.com

Ms. Carolyn Coder
Registered Environmental Health Specialist
Mariposa County Health Department
ccoder@mariposacounty.org

Mr. David Conway, Director
Mariposa County Health Department
dconway@maiposacounty.org